



Field Service Bulletin

Water Heaters Damaged By Flooding

Model(s) Affected: All Units

Do not use this appliance if any part has been under water. Immediately call a Qualified Service Technician to inspect the appliance and to replace any part of the control system, and any gas control (including the Defender Safety System ® and associated components), which has been under water.

Depending upon individual circumstances, it may be necessary to replace the entire water heater.

ENGINEERED FOR THE PLUMBING TRADE

"A WHOLESALE COMMITMENT TO YOUR SUCCESS"